

Early Birds Your GM Muscle Car Headquarters

Visit www.early-birds.ca for most up-to-date catalog this copy was generated March 29 2024

El Camino / Body Panels / Cowl, Dash & Firewall

Picture	Product name	Description	SKU	CAD			
35.							
Basers View 1	1964-1967 Firewall (Heater Delete)	Excellent quality reproduction manufactured to duplicate the original in both fit and appearance.	ELD1461IA	624.00			
1	1964-1967 Windshield Channel (Weld Through Primer)	Excellent quality reproduction manufactured to duplicate the original in both fit and appearance. Weld Through Primer.	ELD1490DWT	93.00			
	1964-1972 Toe Board - LH	This is the piece that attaches to the front section of the floor pan and extends up the firewall towards the brake booster.	ELTBLH6472	92.21			
	1964-1972 Toe Board - RH	This is the piece that attaches to the front section of the floor pan and extends up the firewall towards the brake booster.	ELTBRH6472	92.21			
Early Birds Order Hotline: 1 800 463 0546							
Market Self-ref							
Underside View	1966 COWL LOWER REAR SECTION	Excellent quality reproduction manufactured to duplicate the original in both fit and appearance.	ELD1419K	360.00			
Set Sur Sur35's 4 375's 4' Wright							
10 les.	1966 LOWER COWL UPPER SECTION	Excellent quality reproduction manufactured to duplicate the original in both fit and appearance.	ELD1419J	231.00			
6.35							
1	1966-1967 Cowl Side Front Panel - LH	The front area of the cowl side. ÊFixes rust in the lower section which is very common.	ELD1419H	111.00			
1	1966-1967 Cowl Side Front Panel - RH	The front area of the cowl side. ÊFixes rust in the lower section which is very common.	ELD1419G	111.00			
D	1066-1067 Cowl Side Higgs Popel (w/AC)	The lower area of the could side and A siles is about a relative to	ELAM276 2400 L	240.59			
	1966-1967 Cowl Side Hinge Panel (w/AC)- LH	The lower area of the cowl side and A pillar is always rusted and now you can fix the problem with our entire cowl side panel. Runs all the way to the bottom of the A pillar and includes all the bends and contours of the original. ÊYou will also need part AM376-3466-4L, Reinforcement, to complete repairs. These two pieces are sandwiched together.	LLAIVIS / 0-3400-L	249.58			
_ /							



all the way to the bottom of the A pillar and includes all the bends and contours of the original. ÉYou will also need part AM376-3466-4R, Reinforcement, to complete repairs. These two pieces are sandwiched together.

249.58



1966-1967 Cowl Side Hinge Panel Lower Reinforcement - LH

This thick, heavy duty piece is used in conjuction with cowl side

ELAM376-3466-4L

124.78

AM376-3466-4L

ichnocond in the Apillar.



1966-1967 Cowl Side Hinge Panel Lower Reinforcement - This thick, heavy duty piece is used in conjuction with cowl side ELAM376-3466-4R 124.78 RH EAM376-3466-4R. ÈTogether these parts will repair rust that is

common at the bottom of the A pillar.



 1966-1967 Cowl Side Outer Panel - LH
 The outer portion of the cowl side
 ELAM376-3466-2L
 124.78



 1966-1967 Cowl Side Outer Panel - RH
 The outer portion of the cowl side
 ELAM376-3466-2R
 124.78




1966-1967 FIREWALL Excellent quality reproduction manufactured to duplicate the ELD1461I 624.00

original in both fit and appearance.




 1968 STEEL DASH PANEL
 1-steel dash panel
 ELD1455
 689.00



1968 STEEL DASH PANEL (Weld Through Primer) Excellent quality reproduction manufactured to duplicate the ELD1455WT 663.00 original in both fit and appearance. Weld through primer



1968-1969 COWL PANEL COMPLETE (Weld Through Excellent quality reproduction manufactured to duplicate the ELD1419AWT 628.00 Primer) coriginal in both fit and appearance. Weld Through Primer



1968-1969 COWL TOP VENT PANEL (Weld Through Primer) Excellent quality reproduction manufactured to duplicate the ELD1418ZWT 360.00

original in both fit and appearance. Weld Through Primer



1968-1969 FIREWALL WIPER PLATE 1-Plate to fit wiper motor to firewall ELD1461G 48.00



1968-1972 Cowl Grille Set (w/AC) - 3Pc Cowl grilles come and go but our premium quality cowl grilles ELTP4511 47.43

stay forever. Many original cowl grilles became brittle, broken and then fell off. Don't allow that to happen again with a cheap replacement. With air, 3 piece set. For cars with vacuum actuator on right hand side. Original GM part # 546425. 1968-1972 Cowl



1968-1972 Cowl Grille Set (w/o AC) - 3Pc

Cowl grilles come and go but our premium quality cowl grilles ELTP4510 stay forever. Many original cowl grilles became brittle, broken and then fall off. Don't allow that to happen again with a cheap replacement. Non air, 3 piece set. Original GM part # 546426. 1968-1972 Cowl Grille Set

47.43



1968-1972 Cowl Outer Hinge Panel (Weld Through Primer) - Excellent quality reproduction manufactured to duplicate the ELD1419FWT

original in both fit and appearance. Weld Through Primer

96.00



1968-1972 Cowl Outer Hinge Panel (Weld Through Primer) - Excellent quality reproduction manufactured to duplicate the ELD1419EWT 96.00

original in both fit and appearance. Weld Through Primer



1968-1972 Cowl Screen Wire Mesh We've now reproduced the correct cowl screen wire mesh used ELPPZCSM6872 47.98

on most GM A-body cars. It is die cut and hot galvanized dipped and powder coated black, so there are no fraved edges. Fits 68 69 70 71 72 Chevelle, El Camino, GTO, LeMans, Cutlass, 442, Skylark, GS models.



1968-1972 COWL SHOULDER PANEL (Weld Through Excellent quality reproduction manufactured to duplicate the ELD1419DWT 274.00 Primer) - LH original in both fit and appearance. Weld Through Primer





1968-1972 COWL SHOULDER PANEL (Weld Through Excellent quality reproduction manufactured to duplicate the ELD1419CWT 274.00

Primer) - RH

original in both fit and appearance. Weld Through Primer



1968-1972 Firewall A/C Delete Aluminum Plate Lightweight and strong, this item is strong enough to mount after ELPPZACDP65 111.29

market ignition system on any other electronics. This is an exact fit, no cutting or drilling required. Each panel is cut to factory This panel meets and exceed IVHRA specifications. requirements. This panel comes in a semi polished finish or can be painted to suit the customers needs.Fits 1968-72 Chevelle / El Camino / Skylark / GS / Cutlass / 442 / GTO / LeMans; 1970-72 Monte Carlo, and 1965-70 Impala. Sold individually



1968-1972 Firewall Brackets - PR 246.00 Excellent quality reproduction manufactured to duplicate the ELD1461F original in both fit and appearance.

1968-1972 Firewall with A/C Excellent quality reproduction manufactured to duplicate the ELD1461A

original in both fit and appearance.

599.00



	1968-1972 Firewall with heater delete	Excellent quality reproduction manufactured to duplicate the original in both fit and appearance.	ELD1461C	599.00
	4000 4070 Firewall without A/O	Funding to polity and dusting property and to dusting the	ELD4464D	500.00
	1968-1972 Firewall without A/C	Excellent quality reproduction manufactured to duplicate the loriginal in both fit and appearance.	ELD1461B	599.00
000				
	1968-1972 GM A-Body Top of Cowl Plug Kit - 4PC	These are an exact reproduction of the originals. These are I brand new factory correct reproductions. They are the correct size, shape, and made from the correct plastic	ELITINL12129	6.72
To time 1º curi d' Noige 1be.				
	1968-1972 Rocker to Cowl Reinforcements - PR	Excellent quality reproduction manufactured to duplicate the I original in both fit and appearance.	ELD1419L	218.00
Flereise View	1970-1972 COWL GRILLE PANEL (Weld Through Primer)	Excellent quality reproduction manufactured to duplicate the loriginal in both fit and appearance.Weld Through Primer	ELD1471CWT	349.00
II				
	1970-1972 Hood Stop Studs - PR	New hood stop studs that mount on cowl firewall. 2 are used per lacar. These lock the hood in back. Sold as pair. These have the special head with OCO raised on them. GM #3976679	ELPPZ3976679	25.58
13CCUC				

1970-1972 LOWER COWL PANEL COMPLETE (Weld Excellent quality reproduction manufactured to duplicate the ELD1419WT

original in both fit and appearance. Weld Through Primer

723.00

Early Birds specializes in hard-to-find El Camino parts and has been serving you for over 25 years. Call us at 1 800 463 0546 Mon - Fri 9:00 AM - 4:00 PM (EST) - we know our cars! Fax your order: (416) 630 8794

Through Primer)

Our Mailing Address: Early Birds 25 Saunders Road, Unit 9 Barrie, Ontario L4N 9A7 Canada